



FIGURE 2. KIT AZ CONTENTS (STEP 1) FLU-8A/P KIN 9398LKAZ19884LX

- 24

ENCLOSURE (20)








FIGURE 4. PROTECTIVE COVER MODIFICATION (STEP 35)




FIGURE 5. REMOVAL OF CASING RETAINING LOOPS (STEP 36)




FIGURE 6. INSTALLATION OF GROMMET (STEP 2h)




FIGURE 7. REMOVAL OF OLD LOCKING PIN COVERS (STEP 4a)




FIGURE 8. POSITION OF GROMMET PAHEL (STEP -6)




FIGURE 9. POSITION OF LOCKING PIN COVER (STEP 4c)





FIGURE 10. POSITION OF HANDLE SNAPS & GROMMET (STEP 44)






FIGURE 11. TEMPLATE FOR LOCATION OF BEADED INFLATION HANDLE, SNAPS & GROMMET (STEP 4d)




FIGURE 12. LABEL PREPARATION (STEP 5a & 5b) KIT A1 KIN 9398LKA118771LX




FIGURE 13. LABEL PREPARATION (STEP 5a & 5b)
KIT A2 KIN 9398LKA219884LX KIT A3 9398LKA320148 LX




FIGURE 14. LAREL LOCATIONS (STEP 5c)




FIGURE 15. INSPECTION OF AUTOMATIC INFLATION DEVICE (STEP 6e)





FIGURE 16. PACKAGING CORD LOOP (STEP 6f)






FIGURE 17. PROTECTIVE COVER INSTALLATION (STEP 66)




FIGURE 18. BEADED INFLATION HANDLE (STEPS 7a, b & 8d,& e)




FIGURE 19. ATTACHING BEADED INFLATION HANDLE TO FIU-8A P AUTOMATIC INFLATION (STEP 78 2 8d





FIGURE 20. INSTALLATION OF FLU-8/P OR FLU-8A/F AUTOMATIC INFLATION DEVICE (STEP 9a)



DETAIL H

FIGURE 21. CO2 CYLINDER INSTALLATION (STEP 96, 94, 3e)




FIGURE 22. BATTERY INSTALLATION (STEP 8c, 10e)




FIGURE 23. BATTERY TESTING (STEP 116)





FIGURE 24. CASING FLAPS FOLDED TOGETHER (STEP 13a)



NOTE:

RIGHT LOBE SHOWN

FIGURE 25. BEADED INFLATION HANDLE ASSEMBLED WITH LIFE PRESERVER CASING (STEP 13b, 13c, 13d

6033 7405 25 Sep 1980

From: Commander, Naval Air Development Center

To: Commending Officer, Naval Air Tochnical Services Facility 700 Robbins Avenue, Philadelphia, PA 19111

Subj: Aircrew Systems Change No. 398, Bev A: forwarding of

Ref: (a) Aeronautical Requirement 41

(b) MAS Oceans, VA mag 1613232 SEP 80

Encl: (1) Aircrew Systems Change No. 398, Rev A entitled "LPA-2, LPU-21/P, LFU-23/P and LPU-24/P Life Preserver Assemblies For Ejection Seat Aircraft Only, Modification For Incorporation of the FLU-8A/P Automatic Inflation Devices; instructions for (WUC 9681100)"

- 1. Enclosure (1), prepared by authority of MAVATR Instructions 5400.14 and 5400.15 and verified in accordance with reference (a), is forwarded for expeditious publication and Fleet distribution. The subject change has been verified with no discrepancies noted and confirmed by reference (b).
- 2. Request this change be distributed to all foreign countries having Fighter and Attack Aircraft procured through Poreign Hilitary Sales in accordance with MAVAIR Instruction 5605.3A CH-2.
- 3. Direct liminou pertinent to the subject change may be maintained with this Center, Mr. J. Lowyckyj, Autovon 441-2460/2412.

J. MANDING By direction

Copy to:
GCMMAVAIRPAC (721)
CCMMAVAIRLANT (522.E)
GMATRA (51113)
CMAVRUS (3214)
MAVAIR (AIR-53116/-4114A3/-04A2C)
MAVSAFECEN, Rorfolk
MAVAIRTECHSERVFAC (216), Philadelphia
MAVAVALOGCEN (2411), Paturent River
ASO (100-44), Philadelphia
WATTC, Lakehurst

GenFiles CREDF 60DF 6C02 603 Files -6033 603312 J. LEWYCKYJ, hsj., 9/25/80; 2400

ENCLOSURE (21)

| | No. of Copies |
|--|---------------|
| H. Koch & Sons, Anaheim, CA | 1 |
| Conax Corp | 2 |
| ILC Dover | 1 |
| U.S. Dept of the Interior, Office of Aircraft Services (1 for L. Langdon) | 1 |
| Union Carbide Corp | 1 |
| Hi-Shear Corp | 1 |
| Vought Corp | 1 |
| (1 for E. R. Atkins Dept. 2-51753) | _ |
| Dayton T. Brown, Inc | 1 |
| (1 for Test Laboratory Division) | |
| Commanding General, U.S. Army Aeromedical Research Lab, | |
| Ft. Rucker | 1 |
| Commanding General, ARNG Safety Office, Aberdeen | - |
| Proving Grounds | 1 |
| Commanding General, HQ, ASD, Wright-Patterson AFB (3 for Ken Troup) | 3 |
| Commanding General, U.S. Army Aviation Systems Command, | |
| St. Louis | 1 |
| Commanding General, HQ, Fifth Army, Ft. Sam Houston (1 for Mr. A. B. C. Davis) | 1 |
| Commanding General, U.S. Army Combat Developments | |
| Activity, (Alaska), TRADOC, Ft. Richardson | 1 |
| Commanding Officer, David W. Taylor Naval Ship | |
| Research and Development Center | 1 |
| (1 for Fire Fighting and Survivability Branch) | |
| Commanding General, U.S. Army Agency for Aviation | |
| Safety, Ft. Rucker | 1 |
| Commanding General, U.S. Army Research Institute | |
| of Environmental Medicine, Natick | 1 |
| Commanding General, U.S. Army Flight Facility, St. Paul | 1 |
| Commanding Officer, VXE-6 | 1 |
| Commanding General, HQ, TRADOC, Ft. Monroe | 1 |
| Commanding General, HHC, 22 Avn Bn, Ft. Wanwright | 1 |
| David Clark Company, Inc | 1 |
| Payne Inc | 1 |
| Grumman Aerospace Corp | 1 |
| Lockheed Aircraft Corp | 1 |
| United Aircraft Corp | ī |
| General Dynamics Corp | ĩ |
| McDonnell Douglas Corp | |

| No. of Copies |
|--|
| Commanding Officer, Naval Air Rework Facility, Naval |
| Engineering Support Office |
| (2 for Code 321) |
| Commanding Officer, FITRON THREE ZERO ONE |
| Commander, Chief of Naval Reserve |
| (1 for Code 57) |
| Commanding Officer, VC-13 |
| Commanding Officer, VF-302 |
| Commanding Officer, Fighter Squadron THREE ZERO TWO |
| Commanding Officer, HELSUPPRON ONE |
| Commanding Officer, Naval Regional Medical Center, |
| Portsmouth |
| Commanding Officer, NAS North Island |
| (1 for Code 582) |
| Commanding General, 3rd MAW (FMFPAC Representative) 1 |
| Commanding General, 1st MAW, FMFPAC |
| |
| Commanding Officer, MAG-24, 1st MAR BDE |
| (1 for Code 81) |
| |
| Chief Naval Air Training |
| |
| Commander, Naval Air Force U.S. Atlantic Fleet |
| (1 for Code 522E) |
| Commanding Officer, HC-16 |
| commanding Utilicer, nC-1 |
| Commanding Officer, FASOTRAGRUPAC |
| Commanding Officer, Naval Air Engineering Center, ESSD 1 |
| (1 for Code 9312) |
| Commanding Officer, MAG-31 |
| Officer in Charge, Branch Clinic, NAS Brunswick 2 |
| Commanding Officer, Naval Weapons Station |
| (2 for Code 3023) |
| Commanding Officer, HS-84 |
| Commanding General, 2nd Marine Aircraft Wing 1 |
| Commanding Officer, MAG-26, 2nd MAW, FMFLANT |
| Office in Charge, Naval Sea Systems Command |
| Detachment, Combatant Craft Engineering |
| Department, Norfolk |
| Director, National Aeronautics and Space |
| Administration, Houston |
| Commandant, U.S. Coast Guard Headquarters, |
| Office of Research & Development |
| Officer in Charge, U.S. Navy Clothing and |
| Textile Research Facility, Natick |
| Canadian Armed Forces, National Defense |
| Headquarters, Ottawa, Canada |
| Commanding Officer, Naval Avionics Center |
| (1 for Code D432) |

DISTRIBUTION LIST

REPORT NO. NADC-81226-60

AIRTASK NO. A531531 #001/75310000

| | | No. of Copies |
|----|---|---------------|
| | Commander, Chief of Naval Operations | 1 |
| | Commander, Naval Air Systems Command | 6 |
| | (1 for AIR-4114A) (1 for AIR-340B) | |
| | (1 for AIR-09E) | |
| | Commanding Officer, Naval Aviation Schools Command | 2 |
| | Commanding Officer, FASOTRAGRUPAC | 1 |
| | Commander, Naval Weapons Center | 5 |
| | Commander, Pacific Missile Test Center | 1 |
| | Commander, Naval Safety Center | 2 |
| | Chief of Naval Education & Training | ī |
| | (1 for Code 421) | • |
| | Commanding Officer, MAWTS-1 | 1 . |
| 7. | Commanding Officer, Aviation Supply Office | • 3 |
| | (2 for Code TEO44-A) | • |
| | Commander, Naval Air Force, U.S. Pacific Fleet | 3 |
| | (1 for Mr. Ben Withers) | |
| | (1 for Code 7212) | |
| | (1 for Code 711) | |
| | Officer In Charge, Naval Regional Medical Center Aviation | |
| | Physiology Training Service | 1 |
| | Commanding Officer, U.S. Coast Guard Air Station, | |
| | San Diego | 2 |
| | Marine Corps Development & Education Command Air Branch, | _ |
| | Fire Power Division, Development Center | 2 |
| | Commander, Light Attack Wing Pacific | 1 |
| | (1 for Code 9733) | |
| | Commanding Officer, Naval Air Technical Services Facility . | 1 |
| | Commanding Officer, Naval Air Rework Facility | 1 |
| | (1 for Code 3331) | • |
| | Commanding Officer, H&HS-48 MACG-48 | 2 |

